



Änderungsindex Software S168 813 Standard
 Release notes software S168 813

Version	Freigabe	English
1.3.3	22.01.13	<p>Short description / main change / reason for new version</p> <p>Bug fixes:</p> <ul style="list-style-type: none"> • OpenProtocol: MID 38 rejected (PRR-02248) • OpenProtocol: Not reply was sent to MID 110 (PRR-02253) • Bomb in Advanced screen if tool #1 is not installed (PRR-02249) • CSV files not sent after Linking group changed in Barcode enabled mode (PRR-01994, partly) • Button in Diagnostics for CSV/XML files displayed wrong (PRR-01726, partly)
1.3.4	10.04.13	<p>Bug fixes:</p> <ul style="list-style-type: none"> • OpenProtocol: MID 110 sends back NOK response (S-00604, GSD PRR-04000) • OpenProtocol: Error bits not supported (S-00604, PRR-04000) • OpenProtocol: Synchronization added to MID0127 to delay the acknowledge packet until the job canceled by the controller. • Fixed several ToolsNet Client problems. (PRR-03699) • Changed plausibility check for Calibration value to allow up to 20000 Nm • WinSPC: fixed crash with long traces (PRR-02414) • AutoSelect in in Run Screen not functional (PRR-02245, CQA-900) • Latest Rundown not shown on Run Screen (PRR-02361) • Controller name with Cyrillic characters was not transmitted (PRR-02390) • Could not leave Run Screen after Tool Change (PRR-02326)
1.4.0	23.04.13	<p>New Features / Enhancements:</p> <ul style="list-style-type: none"> • Support for up to 4 LiveWire I-Wrenches • Sequence 32 (Prevailing Torque, compensated) • Sequence 33 (Pulse Torque Recovery) • LiveWire Tools now support 96 Linking positions instead of 40 • Possibility to configure 5 GHz band U-NII 2, 2ex and 3 for LiveWire Tools • Ability to delete Applications (S-00329) • Software Update Utility V1.3 with improved error checking and Software Update Report via FTP as XML • Data Transfer in selected Torque unit for OpenProtocol MID 61 and 101, also for Fieldbus data transfer • Ability to accept System Bus map automatically • Option to lock tools if fieldbus is disconnected • Support for 2-port EtherNet/IP module with M12 connectors (544278PT) • Performance improvement in Anybus drivers <p>Bug fixes:</p> <ul style="list-style-type: none"> • Not possible to show diagnostics information for Spindles and hand tools in various scenarios (PRR-02210, PRR-02224) • Secondary controller shows error TDR1 with Tubenut tools (PRR-02176, CQA-777) • Tubenut tools - max torque and backoff speed set wrong (PRR-00439, CAQ-819) • Auto Select not functional (PRR-02245, CQA-900)
1.4.1	28.08.13	<p>New Features / Enhancements:</p> <ul style="list-style-type: none"> - Maximum Part ID barcode length is now 39 characters for all tools (32 with work piece administration) - Made sequence of VIN reception and Linking Group selection arbitrary in Part ID interlocked mode - Faster upload of jobs and applications to I-Wrench - Made Secondary display configurable to show Job information and other Torque Units than Nm - Better detection for offline results which don't belong to the current work piece (Job mismatch) - Displaying free space in system partition in Net / Proc window - Removed unnecessary log messages <p>Bug fixes:</p> <p>PRR-02645 Input and Output signals not saved in Advanced AB</p> <p>PRR-02603 Installation error in Tool Setup</p> <p>PRR-02219 Linking and Position programming in mPro</p> <p>PRR-02621 Loading Graphics Time-Out Recovery was missing</p> <p>PRR-02618 Torque transmitted on OpenProtocol, Fieldbus is not in Nm if other TQ unit is selected</p> <p>PRR-02650 Duplicate results in CSV files</p> <p>PRR-02183 Output 'Tool Enabled' is active even if no application is selected</p> <p>PRR-01936 No data sent over OpenProtocol for some time if HD Archive is cleared</p> <p>PRR-02625 Barcode not functional with LiveWire</p>

<p>1.4.2</p>	<p>20.02.2014</p>	<p>New Features / Enhancements:</p> <ul style="list-style-type: none"> - Support for Standard2 with Part ID Protocol - Using volatile RAM for RAM Archive instead of battery RAM to increase buffer size - Improved statistics with new filter options - Improved terminology for Linking Groups, Linking Steps, Tightening Position, etc. - Reduced general CPU load - Added System Info for LiveWire Tools - Added network info for secondary network card in Net/Proc window - Merge new configuration option dialog for I-Wrench from BMW software - Merged from branch 1.3.3-B: <ul style="list-style-type: none"> o Additional Options for CSV Data transmission: Prefix, Time Sync, work piece OK, Filename without century, French column headers o Scanner Prefix is now configurable – multiple scanned can now be used for multiple tools with one base station <p>Bug fixes:</p> <table border="0"> <thead> <tr> <th style="text-align: left;">Number</th> <th style="text-align: left;">Name</th> <th style="text-align: right;">CQA</th> </tr> </thead> <tbody> <tr> <td>PRR-02868</td> <td>PRR - Controller gets very slow</td> <td style="text-align: right;">1756</td> </tr> <tr> <td>PRR-02856</td> <td>PRR - Process schraube crash if Linking group is changed during rundown</td> <td></td> </tr> <tr> <td>PRR-02746</td> <td>PRR - Date changes on our controller automatically when it connects to ToolsNet</td> <td></td> </tr> <tr> <td>PRR-02718</td> <td>PRR - Not able to run applications if first tool number does not match the group number</td> <td></td> </tr> <tr> <td>PRR-02655</td> <td>PRR - OP - Batch counter incremented at first NOK in OK counting mode</td> <td></td> </tr> <tr> <td>PRR-02824</td> <td>PRR - Archive vertical alignment wrong</td> <td></td> </tr> <tr> <td>PRR-02717</td> <td>PRR - Rundown not archived if TQ cal is greater than 10000 Nm</td> <td style="text-align: right;">1471</td> </tr> <tr> <td>PRR-02834</td> <td>PRR - Serial Barcode Prefix not functional</td> <td></td> </tr> <tr> <td>PRR-02832</td> <td>PRR - Bitmap Image and Multiple Tools</td> <td style="text-align: right;">1719</td> </tr> <tr> <td>PRR-00835</td> <td>PRR - Only one barcode length possible with work piece administration</td> <td></td> </tr> <tr> <td>PRR-02719</td> <td>PRR - Spindles Not locked for reverse when the spindle Bypass is activated</td> <td></td> </tr> <tr> <td>PRR-02886</td> <td>PRR - Timer based SE signal is always high during rundown</td> <td></td> </tr> <tr> <td>PRR-02703</td> <td>PRR - Tool Enable missing source messages not implemented completely</td> <td></td> </tr> </tbody> </table>	Number	Name	CQA	PRR-02868	PRR - Controller gets very slow	1756	PRR-02856	PRR - Process schraube crash if Linking group is changed during rundown		PRR-02746	PRR - Date changes on our controller automatically when it connects to ToolsNet		PRR-02718	PRR - Not able to run applications if first tool number does not match the group number		PRR-02655	PRR - OP - Batch counter incremented at first NOK in OK counting mode		PRR-02824	PRR - Archive vertical alignment wrong		PRR-02717	PRR - Rundown not archived if TQ cal is greater than 10000 Nm	1471	PRR-02834	PRR - Serial Barcode Prefix not functional		PRR-02832	PRR - Bitmap Image and Multiple Tools	1719	PRR-00835	PRR - Only one barcode length possible with work piece administration		PRR-02719	PRR - Spindles Not locked for reverse when the spindle Bypass is activated		PRR-02886	PRR - Timer based SE signal is always high during rundown		PRR-02703	PRR - Tool Enable missing source messages not implemented completely	
Number	Name	CQA																																										
PRR-02868	PRR - Controller gets very slow	1756																																										
PRR-02856	PRR - Process schraube crash if Linking group is changed during rundown																																											
PRR-02746	PRR - Date changes on our controller automatically when it connects to ToolsNet																																											
PRR-02718	PRR - Not able to run applications if first tool number does not match the group number																																											
PRR-02655	PRR - OP - Batch counter incremented at first NOK in OK counting mode																																											
PRR-02824	PRR - Archive vertical alignment wrong																																											
PRR-02717	PRR - Rundown not archived if TQ cal is greater than 10000 Nm	1471																																										
PRR-02834	PRR - Serial Barcode Prefix not functional																																											
PRR-02832	PRR - Bitmap Image and Multiple Tools	1719																																										
PRR-00835	PRR - Only one barcode length possible with work piece administration																																											
PRR-02719	PRR - Spindles Not locked for reverse when the spindle Bypass is activated																																											
PRR-02886	PRR - Timer based SE signal is always high during rundown																																											
PRR-02703	PRR - Tool Enable missing source messages not implemented completely																																											
<p>1.4.3</p>	<p>04.07.2014</p>	<p>New Features / Enhancements:</p> <ul style="list-style-type: none"> - Support for multiple serial scanners connected to one serial port. A prefix can be assigned to each tool to distribute barcodes from multiple scanners to multiple tools. - Support for one serial scanner for multiple tools - EtherNet/IP Beacon-based DLR module supported <p>Bug fixes:</p> <table border="0"> <thead> <tr> <th style="text-align: left;">Number</th> <th style="text-align: left;">Name</th> <th style="text-align: right;">CQA</th> </tr> </thead> <tbody> <tr> <td>PRR-02991</td> <td>Duplicate Results from I-Wrench</td> <td></td> </tr> <tr> <td>PRR-02850</td> <td>Part ID change during rundown causes multiple results in Archive</td> <td style="text-align: right;">1744</td> </tr> <tr> <td>PRR-03008</td> <td>FEP: MID 0013: Batch size transmitted wrong</td> <td></td> </tr> <tr> <td>PRR-02980</td> <td>Could not setup output timers if tool group #1 not installed</td> <td></td> </tr> <tr> <td>PRR-03033</td> <td>Customize settings for unexpected barcodes</td> <td></td> </tr> <tr> <td>PRR-03009</td> <td>Visualization text of the linking step not displayed the tool display</td> <td></td> </tr> <tr> <td>PRR-03010</td> <td>Cannot use tools after startup with Linking Screen as startup visualization</td> <td></td> </tr> <tr> <td>PRR-02987</td> <td>Part ID entered through keyboard is not accepted in Ext Application mode</td> <td></td> </tr> <tr> <td>PRR-02990</td> <td>The Tool constants screen does not accept high angle factors</td> <td></td> </tr> <tr> <td>PRR-02939</td> <td>For X LiveWire models it is not possible to set the Wireless channel</td> <td style="text-align: right;">1870</td> </tr> </tbody> </table>	Number	Name	CQA	PRR-02991	Duplicate Results from I-Wrench		PRR-02850	Part ID change during rundown causes multiple results in Archive	1744	PRR-03008	FEP: MID 0013: Batch size transmitted wrong		PRR-02980	Could not setup output timers if tool group #1 not installed		PRR-03033	Customize settings for unexpected barcodes		PRR-03009	Visualization text of the linking step not displayed the tool display		PRR-03010	Cannot use tools after startup with Linking Screen as startup visualization		PRR-02987	Part ID entered through keyboard is not accepted in Ext Application mode		PRR-02990	The Tool constants screen does not accept high angle factors		PRR-02939	For X LiveWire models it is not possible to set the Wireless channel	1870									
Number	Name	CQA																																										
PRR-02991	Duplicate Results from I-Wrench																																											
PRR-02850	Part ID change during rundown causes multiple results in Archive	1744																																										
PRR-03008	FEP: MID 0013: Batch size transmitted wrong																																											
PRR-02980	Could not setup output timers if tool group #1 not installed																																											
PRR-03033	Customize settings for unexpected barcodes																																											
PRR-03009	Visualization text of the linking step not displayed the tool display																																											
PRR-03010	Cannot use tools after startup with Linking Screen as startup visualization																																											
PRR-02987	Part ID entered through keyboard is not accepted in Ext Application mode																																											
PRR-02990	The Tool constants screen does not accept high angle factors																																											
PRR-02939	For X LiveWire models it is not possible to set the Wireless channel	1870																																										

1.4.4	17.10.2014	<p>New Features / Enhancements:</p> <ul style="list-style-type: none"> • OpenProtocol: New Setting to allow or disallow Linking Group termination with MID0038 • OpenProtocol: New setting for reset Batch size to zero on Connection Loss • Tightening: Evaluation Torque setting to ignore all results below this value (per tool group) • Data Export: Stage results selectable • Data Export: Decimal separator configurable <p>Bug fixes:</p> <table border="0"> <thead> <tr> <th>Number</th> <th>Name</th> <th>CQA</th> </tr> </thead> <tbody> <tr> <td>PRR-02838</td> <td>MID0410 - For auto disable request no ACK or NAK response is received</td> <td></td> </tr> <tr> <td>PRR-03064</td> <td>Deleting application in Matrix tab is not deleting application information completely</td> <td>2088</td> </tr> <tr> <td>PRR-03090</td> <td>Gradient values are populated in export of Seq. 32 and no PVT value available</td> <td></td> </tr> <tr> <td>PRR-03108</td> <td>Differences on serial Interface with v1.4.0 to 1.4.3</td> <td>2356</td> </tr> <tr> <td>PRR-03109</td> <td>Barcode scan step configured from mPro linking screen saves only 16 characters</td> <td></td> </tr> <tr> <td>PRR-03110</td> <td>Five-decimal values for Brake Rope Adjustment parameters are changed unintentionally</td> <td></td> </tr> <tr> <td>PRR-03113</td> <td>Skips of a linking step when scan of barcode step with different tool is done</td> <td></td> </tr> <tr> <td>PRR-03138</td> <td>MID0019 - Set Batch is accepted even though batch is inactive for application</td> <td></td> </tr> <tr> <td>PRR-03140</td> <td>Terminology for Linking Group parameters not used consistently</td> <td>2383</td> </tr> <tr> <td>PRR-03169</td> <td>Tool data for Livewire tools not always available when user acceptance is needed</td> <td>2358</td> </tr> </tbody> </table>	Number	Name	CQA	PRR-02838	MID0410 - For auto disable request no ACK or NAK response is received		PRR-03064	Deleting application in Matrix tab is not deleting application information completely	2088	PRR-03090	Gradient values are populated in export of Seq. 32 and no PVT value available		PRR-03108	Differences on serial Interface with v1.4.0 to 1.4.3	2356	PRR-03109	Barcode scan step configured from mPro linking screen saves only 16 characters		PRR-03110	Five-decimal values for Brake Rope Adjustment parameters are changed unintentionally		PRR-03113	Skips of a linking step when scan of barcode step with different tool is done		PRR-03138	MID0019 - Set Batch is accepted even though batch is inactive for application		PRR-03140	Terminology for Linking Group parameters not used consistently	2383	PRR-03169	Tool data for Livewire tools not always available when user acceptance is needed	2358						
Number	Name	CQA																																							
PRR-02838	MID0410 - For auto disable request no ACK or NAK response is received																																								
PRR-03064	Deleting application in Matrix tab is not deleting application information completely	2088																																							
PRR-03090	Gradient values are populated in export of Seq. 32 and no PVT value available																																								
PRR-03108	Differences on serial Interface with v1.4.0 to 1.4.3	2356																																							
PRR-03109	Barcode scan step configured from mPro linking screen saves only 16 characters																																								
PRR-03110	Five-decimal values for Brake Rope Adjustment parameters are changed unintentionally																																								
PRR-03113	Skips of a linking step when scan of barcode step with different tool is done																																								
PRR-03138	MID0019 - Set Batch is accepted even though batch is inactive for application																																								
PRR-03140	Terminology for Linking Group parameters not used consistently	2383																																							
PRR-03169	Tool data for Livewire tools not always available when user acceptance is needed	2358																																							
1.4.5	14.01.2015	<p>Bug fixes:</p> <table border="0"> <thead> <tr> <th>Number</th> <th>Name</th> <th>CQA</th> </tr> </thead> <tbody> <tr> <td>PRR-03057</td> <td>Parameters in MYPARA are different than saved parameters on e.g. USB-Stick</td> <td></td> </tr> <tr> <td>PRR-03222</td> <td>Tool not locked if invalid bitmask is selected</td> <td></td> </tr> <tr> <td>PRR-03223</td> <td>Process schraube crash if text for inputs used</td> <td>2088</td> </tr> <tr> <td>PRR-03224</td> <td>Parameter changes via mProRemote for application 1-9 not used</td> <td></td> </tr> </tbody> </table>	Number	Name	CQA	PRR-03057	Parameters in MYPARA are different than saved parameters on e.g. USB-Stick		PRR-03222	Tool not locked if invalid bitmask is selected		PRR-03223	Process schraube crash if text for inputs used	2088	PRR-03224	Parameter changes via mProRemote for application 1-9 not used																									
Number	Name	CQA																																							
PRR-03057	Parameters in MYPARA are different than saved parameters on e.g. USB-Stick																																								
PRR-03222	Tool not locked if invalid bitmask is selected																																								
PRR-03223	Process schraube crash if text for inputs used	2088																																							
PRR-03224	Parameter changes via mProRemote for application 1-9 not used																																								
1.4.6	29.06.2015	<p>New Features / Enhancements:</p> <ul style="list-style-type: none"> • I-Wrench new parameters: <ul style="list-style-type: none"> ○ timeouts for finish tightening application after release: <ul style="list-style-type: none"> ▪ if not reached shutoff point (long timeout) ▪ and if reached shutoff point (short timeout) ○ Block error detection parameter minAngleToMinTorque can be set ○ Trigger torque available • I-Wrench graphic points start from trigger torque <p>Additional change: Input signal "ToolEnabled": Signal state is now verified only while starting a rundown. During the tool is running the signal has no influence anymore.</p> <p>Bug fixes:</p> <table border="0"> <thead> <tr> <th>Number</th> <th>Name</th> <th>CQA</th> </tr> </thead> <tbody> <tr> <td>PRR-03276</td> <td>External Application Selection not functional with I-Wrench</td> <td>2573</td> </tr> <tr> <td>PRR-03281</td> <td>Endless loop with MID0052 and MID0018</td> <td></td> </tr> <tr> <td>PRR-03290</td> <td>Rundown not possible in Manual Mode</td> <td></td> </tr> <tr> <td>PRR-03291</td> <td>Could not enter scan PartId step or barcode step manually and via Fieldbus</td> <td>2641</td> </tr> <tr> <td>PRR-03320</td> <td>MID-0061 takes more than 1000ms</td> <td></td> </tr> <tr> <td>PRR-03346</td> <td>Different VIN transmission to CSV-SAMBA</td> <td></td> </tr> <tr> <td>PRR-03359</td> <td>I-Wrench does not work with torque multiplier</td> <td></td> </tr> <tr> <td>PRR-03361</td> <td>OP MID 42 and MID 43 with I-Wrench does not work with fast commands</td> <td></td> </tr> <tr> <td>PRR-03363</td> <td>No Job loaded to TMA after leaving Manual mode</td> <td></td> </tr> <tr> <td>PRR-03366</td> <td>OP Job select MID0038 takes more than 4s</td> <td></td> </tr> <tr> <td>PRR-03373</td> <td>Scanner LiveWire Tools is not activated in Manual Operation mode with Part ID</td> <td></td> </tr> <tr> <td>PRR-03425</td> <td>OP MID-0127 Linking Group gets reselected immediately when not in Runscreen</td> <td></td> </tr> </tbody> </table>	Number	Name	CQA	PRR-03276	External Application Selection not functional with I-Wrench	2573	PRR-03281	Endless loop with MID0052 and MID0018		PRR-03290	Rundown not possible in Manual Mode		PRR-03291	Could not enter scan PartId step or barcode step manually and via Fieldbus	2641	PRR-03320	MID-0061 takes more than 1000ms		PRR-03346	Different VIN transmission to CSV-SAMBA		PRR-03359	I-Wrench does not work with torque multiplier		PRR-03361	OP MID 42 and MID 43 with I-Wrench does not work with fast commands		PRR-03363	No Job loaded to TMA after leaving Manual mode		PRR-03366	OP Job select MID0038 takes more than 4s		PRR-03373	Scanner LiveWire Tools is not activated in Manual Operation mode with Part ID		PRR-03425	OP MID-0127 Linking Group gets reselected immediately when not in Runscreen	
Number	Name	CQA																																							
PRR-03276	External Application Selection not functional with I-Wrench	2573																																							
PRR-03281	Endless loop with MID0052 and MID0018																																								
PRR-03290	Rundown not possible in Manual Mode																																								
PRR-03291	Could not enter scan PartId step or barcode step manually and via Fieldbus	2641																																							
PRR-03320	MID-0061 takes more than 1000ms																																								
PRR-03346	Different VIN transmission to CSV-SAMBA																																								
PRR-03359	I-Wrench does not work with torque multiplier																																								
PRR-03361	OP MID 42 and MID 43 with I-Wrench does not work with fast commands																																								
PRR-03363	No Job loaded to TMA after leaving Manual mode																																								
PRR-03366	OP Job select MID0038 takes more than 4s																																								
PRR-03373	Scanner LiveWire Tools is not activated in Manual Operation mode with Part ID																																								
PRR-03425	OP MID-0127 Linking Group gets reselected immediately when not in Runscreen																																								
1.4.7	18.08.2015	<p>Bug fixes:</p> <table border="0"> <thead> <tr> <th>Number</th> <th>Name</th> <th>CQA</th> </tr> </thead> <tbody> <tr> <td>PRR-03440</td> <td>Job mismatch with scanner, scan step (23 characters) for battery tool</td> <td>2894</td> </tr> </tbody> </table>	Number	Name	CQA	PRR-03440	Job mismatch with scanner, scan step (23 characters) for battery tool	2894																																	
Number	Name	CQA																																							
PRR-03440	Job mismatch with scanner, scan step (23 characters) for battery tool	2894																																							
1.4.8	16.10.2015	<p>Bug fixes:</p> <table border="0"> <thead> <tr> <th>Number</th> <th>Name</th> <th>CQA</th> </tr> </thead> <tbody> <tr> <td>PRR-03456</td> <td>Wrong Batch Position Displayed and Transmitted Over Open Protocol</td> <td></td> </tr> </tbody> </table>	Number	Name	CQA	PRR-03456	Wrong Batch Position Displayed and Transmitted Over Open Protocol																																		
Number	Name	CQA																																							
PRR-03456	Wrong Batch Position Displayed and Transmitted Over Open Protocol																																								
1.4.9	26.01.2016	<p>Bug fixes:</p> <table border="0"> <thead> <tr> <th>Number</th> <th>Name</th> <th>CQA</th> </tr> </thead> <tbody> <tr> <td>PRR-03690</td> <td>Application dropdown is not updated on Runscreen</td> <td>3176</td> </tr> <tr> <td>PRR-07710</td> <td>OpenProtocol workflow too slow with LiveWire Tools</td> <td></td> </tr> </tbody> </table>	Number	Name	CQA	PRR-03690	Application dropdown is not updated on Runscreen	3176	PRR-07710	OpenProtocol workflow too slow with LiveWire Tools																															
Number	Name	CQA																																							
PRR-03690	Application dropdown is not updated on Runscreen	3176																																							
PRR-07710	OpenProtocol workflow too slow with LiveWire Tools																																								

1.4.10	03.03.2016	<p>main change:</p> <ul style="list-style-type: none"> ◆ I-Wrench Results won't be accepted if ResultID is older than the last added result ◆ Results with ResultID zero will always be accepted. Can only happen after recirculation of ResultID variable (9.999.999 tightenings) or manipulated EEPROM on the wrench. ◆ Reset of comparison of ResultID after accept tool change. <p>Bug fixes:</p> <table border="0" style="width: 100%;"> <thead> <tr> <th style="text-align: left;">Number</th> <th style="text-align: left;">Name</th> <th style="text-align: right;">CQA</th> </tr> </thead> <tbody> <tr> <td>PRR-03706</td> <td>Results out of order with I-Wrench with bad wireless connection</td> <td></td> </tr> </tbody> </table>	Number	Name	CQA	PRR-03706	Results out of order with I-Wrench with bad wireless connection													
Number	Name	CQA																		
PRR-03706	Results out of order with I-Wrench with bad wireless connection																			
1.4.11	02.09.2016	<p>Bug fixes:</p> <table border="0" style="width: 100%;"> <thead> <tr> <th style="text-align: left;">Number</th> <th style="text-align: left;">Name</th> <th style="text-align: right;">CQA</th> </tr> </thead> <tbody> <tr> <td>PRR-03780</td> <td>Error when change position point in picture</td> <td></td> </tr> <tr> <td>PRR-03835</td> <td>Batch activation does not work properly for LiveWire and OP</td> <td></td> </tr> <tr> <td>PRR-03841</td> <td>Data not transmitted with big traces</td> <td></td> </tr> <tr> <td>PRR-03880</td> <td>OK and NOK set at once if Sequence 46 is used with less than 9°</td> <td></td> </tr> <tr> <td>PRR-03884</td> <td>MID 128 sends no answer</td> <td></td> </tr> </tbody> </table>	Number	Name	CQA	PRR-03780	Error when change position point in picture		PRR-03835	Batch activation does not work properly for LiveWire and OP		PRR-03841	Data not transmitted with big traces		PRR-03880	OK and NOK set at once if Sequence 46 is used with less than 9°		PRR-03884	MID 128 sends no answer	
Number	Name	CQA																		
PRR-03780	Error when change position point in picture																			
PRR-03835	Batch activation does not work properly for LiveWire and OP																			
PRR-03841	Data not transmitted with big traces																			
PRR-03880	OK and NOK set at once if Sequence 46 is used with less than 9°																			
PRR-03884	MID 128 sends no answer																			
1.4.12	29.09.2016	<p>Bug fixes:</p> <table border="0" style="width: 100%;"> <thead> <tr> <th style="text-align: left;">Number</th> <th style="text-align: left;">Name</th> <th style="text-align: right;">CQA</th> </tr> </thead> <tbody> <tr> <td>PRR-03972</td> <td>Process Schraube crash at activation of Manual Mode</td> <td></td> </tr> </tbody> </table>	Number	Name	CQA	PRR-03972	Process Schraube crash at activation of Manual Mode													
Number	Name	CQA																		
PRR-03972	Process Schraube crash at activation of Manual Mode																			

<p>1.5.0</p>	<p>19.12.2016</p>	<p>New Features / Enhancements:</p> <ul style="list-style-type: none"> • Screen Reorganization: Removed mPro button and unified TME and mPro GUI • Multi-Tool Group - Redesign Screens according to style guidelines • Maintenance Counters functionality • 99 Linking Groups can be parameterized • Enhanced traces configurable per tool group • ToolsNet with traces • Speed ramps • Number of bitmaps for visualization set to 40 • FTP / SAMBA now also works in Application mode • Load and save single applications as XML • More than 80 bytes per group in byte area • IPM Protocol • CPS_READY Input (BMW) • Untightened Archive Entries (SKIP) – Results of non-tightening (HONDA Brazil) • Fast trace transmission (GMPT) • Open Protocol: <ul style="list-style-type: none"> ◦ MID 250-255 ◦ Channel IDs configurable • HBPO / LEAR merge: <ul style="list-style-type: none"> ◦ Back-off application configurable • CSV Export for all stages from HD Archive • support TRASYS protocol • New features for I-Wrench: <ul style="list-style-type: none"> ◦ CCW and Seq. 63 ◦ More than 20 steps in Linking Group supported ◦ multiple barcodes support ◦ Seq. 30+50+63 trigger torque configurable ◦ BLOC Angle, short and long timeout configuration ◦ Application/Linking Group selection by socket head • New features for LiveWire tools: <ul style="list-style-type: none"> ◦ Manual Application/Linking Group selection on tool <p>Bug fixes:</p> <table border="0" style="width: 100%;"> <thead> <tr> <th style="text-align: left;">Number</th> <th style="text-align: left;">Name</th> <th style="text-align: right;">CQA</th> </tr> </thead> <tbody> <tr> <td>PRR-00312</td> <td>Speed ramps not adjustable</td> <td style="text-align: right;">0926</td> </tr> <tr> <td>PRR-02583</td> <td>Various issues with torque calibration factor 20000 Nm</td> <td style="text-align: right;">1471</td> </tr> <tr> <td>PRR-02548</td> <td>CSV-FTP loses results if rundown results have same timestamp</td> <td></td> </tr> <tr> <td>PRR-02589</td> <td>Schraube – Cycle time higher than 100 ms</td> <td style="text-align: right;">1113</td> </tr> <tr> <td>PRR-02799</td> <td>FTP-Samba – Seq. 30 limits used for Seq. 11</td> <td></td> </tr> <tr> <td>PRR-02940</td> <td>LiveWire tools – use of single WIFI Channel not functional</td> <td style="text-align: right;">1871</td> </tr> <tr> <td>PRR-02974</td> <td>OK if in limits function not translated</td> <td></td> </tr> <tr> <td>PRR-02976</td> <td>Timer for output signals not functional if Tool 1 is not installed</td> <td></td> </tr> <tr> <td>PRR-03095</td> <td>Workaround for FLT error when stopping spindles is required</td> <td></td> </tr> <tr> <td>PRR-03137</td> <td>I-Wrench BLOC error calculation needs to be improved</td> <td></td> </tr> <tr> <td>PRR-03217</td> <td>Evaluation torque for Back-off with LiveWire tools does not work</td> <td></td> </tr> <tr> <td>PRR-03232</td> <td>Ofmpro crash in case of barcodes including percent characters</td> <td></td> </tr> <tr> <td>PRR-03445</td> <td>Tool is locked by output timer although function not activated</td> <td style="text-align: right;">2906</td> </tr> <tr> <td>PRR-03685</td> <td>No communication for TorqueNet with new TcpClient</td> <td></td> </tr> <tr> <td>PRR-03690</td> <td>Application dropdown is not updated on Runscreen</td> <td style="text-align: right;">3176</td> </tr> <tr> <td>PRR-03780</td> <td>Error by change of tightening point at Visualization screen</td> <td></td> </tr> <tr> <td>PRR-03835</td> <td>Batch activation does not work properly for LiveWire tools and Open Protocol</td> <td></td> </tr> <tr> <td>PRR-03841</td> <td>Data not transmitted with big traces (TorqueNet and ToolsNet)</td> <td></td> </tr> <tr> <td>PRR-03885</td> <td>MID0035 Job info does report wrong job status</td> <td></td> </tr> <tr> <td>PRR-03902</td> <td>Wrong applications in applications dropdown in Runscreen with multi-tool group</td> <td></td> </tr> <tr> <td>PRR-04034</td> <td>Disable LiveWire tools with OP MID0042 not functional</td> <td></td> </tr> </tbody> </table> <p>Known issues with this version:</p> <ul style="list-style-type: none"> • Rundown counters will be cleared after update from Versions S168813-1.4.x • Multi Tool Group setup – Tool Group number does not equal installed Tool number in Tool Group may not work as expected (Will be fixed later) 	Number	Name	CQA	PRR-00312	Speed ramps not adjustable	0926	PRR-02583	Various issues with torque calibration factor 20000 Nm	1471	PRR-02548	CSV-FTP loses results if rundown results have same timestamp		PRR-02589	Schraube – Cycle time higher than 100 ms	1113	PRR-02799	FTP-Samba – Seq. 30 limits used for Seq. 11		PRR-02940	LiveWire tools – use of single WIFI Channel not functional	1871	PRR-02974	OK if in limits function not translated		PRR-02976	Timer for output signals not functional if Tool 1 is not installed		PRR-03095	Workaround for FLT error when stopping spindles is required		PRR-03137	I-Wrench BLOC error calculation needs to be improved		PRR-03217	Evaluation torque for Back-off with LiveWire tools does not work		PRR-03232	Ofmpro crash in case of barcodes including percent characters		PRR-03445	Tool is locked by output timer although function not activated	2906	PRR-03685	No communication for TorqueNet with new TcpClient		PRR-03690	Application dropdown is not updated on Runscreen	3176	PRR-03780	Error by change of tightening point at Visualization screen		PRR-03835	Batch activation does not work properly for LiveWire tools and Open Protocol		PRR-03841	Data not transmitted with big traces (TorqueNet and ToolsNet)		PRR-03885	MID0035 Job info does report wrong job status		PRR-03902	Wrong applications in applications dropdown in Runscreen with multi-tool group		PRR-04034	Disable LiveWire tools with OP MID0042 not functional	
Number	Name	CQA																																																																		
PRR-00312	Speed ramps not adjustable	0926																																																																		
PRR-02583	Various issues with torque calibration factor 20000 Nm	1471																																																																		
PRR-02548	CSV-FTP loses results if rundown results have same timestamp																																																																			
PRR-02589	Schraube – Cycle time higher than 100 ms	1113																																																																		
PRR-02799	FTP-Samba – Seq. 30 limits used for Seq. 11																																																																			
PRR-02940	LiveWire tools – use of single WIFI Channel not functional	1871																																																																		
PRR-02974	OK if in limits function not translated																																																																			
PRR-02976	Timer for output signals not functional if Tool 1 is not installed																																																																			
PRR-03095	Workaround for FLT error when stopping spindles is required																																																																			
PRR-03137	I-Wrench BLOC error calculation needs to be improved																																																																			
PRR-03217	Evaluation torque for Back-off with LiveWire tools does not work																																																																			
PRR-03232	Ofmpro crash in case of barcodes including percent characters																																																																			
PRR-03445	Tool is locked by output timer although function not activated	2906																																																																		
PRR-03685	No communication for TorqueNet with new TcpClient																																																																			
PRR-03690	Application dropdown is not updated on Runscreen	3176																																																																		
PRR-03780	Error by change of tightening point at Visualization screen																																																																			
PRR-03835	Batch activation does not work properly for LiveWire tools and Open Protocol																																																																			
PRR-03841	Data not transmitted with big traces (TorqueNet and ToolsNet)																																																																			
PRR-03885	MID0035 Job info does report wrong job status																																																																			
PRR-03902	Wrong applications in applications dropdown in Runscreen with multi-tool group																																																																			
PRR-04034	Disable LiveWire tools with OP MID0042 not functional																																																																			
<p>1.6.0</p>	<p>22.05.2017</p>	<p>New Features / Enhancements:</p> <ul style="list-style-type: none"> • S-00319 MID 0152 Multiple Identifiers Work Order Upload • S-00324 MID 0157 Reset All Identifiers • S-00722 Implement TPS Support • S-00735 Improve Advanced/Tool Group Settings tabs <p>Bug fixes:</p> <ul style="list-style-type: none"> • PRR-04220 Manual Input Select in Linking Group not working • PRR-04127 Run Screen displays wrong status message • PRR-04182 Lock with bitmask does not work with LiveWire Tools 																																																																		

1.6.1	03.05.2018	<p>New Features / Enhancements:</p> <ul style="list-style-type: none"> • REQ-00408 Compensation Value Seq 32 in Export • REQ-00416 App select on battery tool by Application Name <p>Bug fixes:</p> <ul style="list-style-type: none"> • PRR-04600 SW-Feature Integrated • PRR-04601 Honda Canada - OP rejects Job selection • PRR-04616 Could not execute release phase using Tube-nut tool • PRR-04617 Tubenut open clears Linking OK/NOK • PRR-10829 Tool's LED did not blink, the Stack-light did not blink • PRR-11523 XML protocol incorrect
1.6.2	29.06.2018	<p>New Features / Enhancements:</p> <ul style="list-style-type: none"> • REQ-00432 Output Signal to signal new scanned barcode • REQ-00437 OP Offline inverted function <p>Bug fixes:</p> <ul style="list-style-type: none"> • PRR-11810 ToolsNet parameter change with NOK Result • PRR-11858 ToolsNet Multispindle issue
1.7.0	27.07.2018	<p>Main Changes / Enhancements:</p> <ul style="list-style-type: none"> • REQ-00393 NGDC Tool support • REQ-00414 Default parameters work with Hybrid and Primary • REQ-00420 Support DGD Protocol with Hybrid • REQ-00423 Tool lights functionality for NeoTek • REQ-00424 Sequence 80 with Torque plus Angle shutoff • REQ-00429 EMS Errors in Archive Error table <p>Bug Fixes:</p> <ul style="list-style-type: none"> • PRR-04350 IPM Version 5.2 setting has no effect • PRR-04491 Batch size greater 40 not possible with Battery tools • PRR-04500 Screen Saver Settings Not Preserved • PRR-04546 MID35 does not work after first position NOK repeat • PRR-04556 I-Wrench Linking with Step IOs not working • PRR-04557 XML-CSV cannot enter french accents in subdir field • PRR-04560 Batch count wrong after Battery tool offline • PRR-04565 Special character for WPA Password • PRR-04586 Report Peak Torque via OP • PRR-11606 ABL error during batch count • PRR-11638 Touch up and Error handling causes parameters update via mProRemote • PRR-11591 Not possible to make mProRemote Connection • PRR-11597 TPS Subscription active after TPS restart
1.7.1	06.09.2018	<p>Bug fixes:</p> <ul style="list-style-type: none"> • REQ-00417 MID-0061 Revision 42 • REQ-00433 MID-0061 Revision 500 • REQ-00434 MID-0061 Revision 998
1.7.2	20.09.2018	<p>Bug fixes:</p> <ul style="list-style-type: none"> • PRR-12412 No graphics data transmission with I-Wrench over IPM • PRR-12466 Standard2PartID protocol receives scanned barcode sporadically • PRR-12483 Loading old parameters not possible after software installation • PRR-12485 ToolsNet – No Enhanced Graphics and additional VIN transmission • PRR-12510 ToolsNet – Connection cannot be re-established
1.8.0	21.12.2018	<p>New Features / Enhancements:</p> <ul style="list-style-type: none"> • REQ-00405 Implement Message for FMEA-0059 • REQ-00418 Remote start support for LiveWire tools • REQ-13524 CellCore support • REQ-13554 Integrated Access Point Wifi configuration • REQ-13579 Brake-Rope Adjustment per Tool • REQ-13647 mPro200 Default IP address • REQ-13667 Add USB mouse support • REQ-13668 mPro200 HW configuration <p>Bug fixes:</p> <ul style="list-style-type: none"> • PRR-12703 Tubenut Operation • PRR-12887 With xBUT spindles is tubenut mode activated • PRR-12989 Toolgroup Enabled output is not activated in application mode • PRR-12992 I-Wrench - job mismatch error • PRR-13146 MID 42 ignored in case no LG is active

1.8.1	21.01.2019	New Features / Enhancements: <ul style="list-style-type: none"> • REQ-00419 XiBase9 Version 7 support • REQ-13721 NeoTek - 2D Scanner support • REQ-13723 NeoTek - 2D Scanner – 2nd function button mode Bug fixes: <ul style="list-style-type: none"> • PRR-13270 NoAck Flag for OP subscriptions
1.8.2	08.02.2019	New Features / Enhancements: <ul style="list-style-type: none"> • REQ-13754 Integrate Tool light accessory and brightness settings Bug fixes: <ul style="list-style-type: none"> • PRR-13315 OK/NOK Signals synchronized with AE for Battery tools • PRR-13355 MID 0061 Batch information not available in job mode
1.8.3	18.03.2019	Bug fixes: <ul style="list-style-type: none"> • PRR-13770 Schraube crash with LiveWire Tools and Job mismatch results
1.9.0	03.05.2019	Bug fixes / New functionality: <ul style="list-style-type: none"> • PRR-12598 - Controller freezing on abort linking via PROFINET • PRR-13820 - TRASYS crash • PRR-13943 - Rounding in XML result file inaccurate • REQ-13476 - CellCore - Bluetooth Support • PRR-14002 - Unknown Error 119 • PRR-14012 - Crash in Tool Setup screen
1.10.0	29.05.2019	Bug fixes / New functionality: <ul style="list-style-type: none"> • REQ-14000 - Gyroscope diagnostic dialog • PRR-13258 - Linking in process high even though no LG selected • PRR-13343 - Profinet and Profibus signals on invalid nodes • PRR-13886 - Default parameter use for stage 1 speed 0 rpm • PRR-13910 - Linking in process high even though no LG selected • PRR-14065 - If dialog for remote control is open is message box with attention sign displayed
1.10.1	14.01.2020	New functionality: <ul style="list-style-type: none"> • REQ-14433 - Merge S168813-1.10-P branch (BTS). • REQ-14293 - Merge S168813-1.6.1_B01CKD . • REQ-13769 – The setting“Lock while offline” can be set to [ms].
1.11.0	18.12.2019	Bug fixes / New functionality: <ul style="list-style-type: none"> • PRR-13126 - No communication between Controller and Tool. • PRR-13188 - Wrong application used with external selection. • PRR-14103 - Application selection via Tool menu on CellCore not functional. • PRR-12961 - Tool does not stop when leaving Switchboard. • PRR-14129 - Input TOOL GROUP STOP does not work with TMA tools. • PRR-15300 - Xi Webserver process crash on network scan. • REQ-14032 - Show EEPROM configuration . • REQ-14433 - Merge S168813-1.10-P branch (BTS). • REQ-14293 - Merge S168813-1.6.1_B01CKD . • REQ-13769 – The setting“Lock while offline” can be set to [ms].
1.11.1	15.07.2020	Bug Fixes: <ul style="list-style-type: none"> • PRR-16232: Workpiece number in workpiece admin was limited to 32 characters instead of 39
1.11.2	17.08.2020	Bug fixes: <ul style="list-style-type: none"> • PRR-16358 - Barcode is not visible in run screen, but can be seen in bus monitor • PRR-16369 - Cellcore the setting for the remote start cannot be selected
1.11.3	10.12.2020	Bug Fixes: <ul style="list-style-type: none"> • PRR-16962 - Two CellCore Tools with same IP address are interchanged - Wrong SI data is accepted
1.11.4	04.02.2021	Bug Fixes: <ul style="list-style-type: none"> • PRR-17066 - Skoda Issue - Two Battery tools - remote start - tool dont tighten when pg is changed via open protocol • PRR-17191 - OpenProtocol reports wrong stage if relax stage is missing in result • PRR-17202 - Wrong MID 0061 reporting if release stage is active in Battery Tool

<p>1.12.0</p>	<p>08.07.2020</p>	<p>New functionality:</p> <ul style="list-style-type: none"> • REQ-13793 - Add TSnet test in HW Test • REQ-13949 - Merge MID 0061 rev. 501 (1.9-N branch) • REQ-14006 - Merge 1.10-M, -N, -O, -Q branches • REQ-14678 - Support MID 410 and MID 411 • REQ-14752 Merge 1.7.0-M01 branch • REQ-14759 - Show used network settings if DHCP enabled in Communication screen input fields • REQ-14768 - Merge 1.10-O (Wireless Socket Tray) • REQ-14706- Implement required patches <p>Bug fixes:</p> <ul style="list-style-type: none"> • PRR-14515 - SI data of previously installed tool is shown as online • PRR-15151 - Reassignment of tool is not proper functional if before assigned to other controller • PRR-15697 - Controller hang up after motherboard hardware test • PRR-15701 - Sequence 51 When activating Nut Slip Off Monitoring Anti Necking gets activated as well • PRR-15906 - LiveWire high torques values do not work anymore
<p>1.11.5</p>	<p>12.02.2021</p>	<p>Bug Fixes:</p> <ul style="list-style-type: none"> • PRR-17041 – Trace Recording setting are now working again for LiveWire tools.
<p>1.12.1</p>	<p>08.03.2021</p>	<p>Bug fixes:</p> <ul style="list-style-type: none"> • PRR-17491 – Input/Output bitmask parameters in advanced linking wrong after software update to 1.12.0
<p>1.12.2</p>		<p>New functionality:</p> <ul style="list-style-type: none"> • REQ-15204: Merge S168813.1.4.12-F • REQ-15372: The Report tightening status for "MID0061" is implemented according to FEP spec. The MID revision here is irrelevant. <p>Bug fixes:</p> <ul style="list-style-type: none"> • PRR-17522: TCPClient would crash after activating TorqueNet • PRR-17864: OpenProtocol MID 12 and XML parameter export would abort with error • PRR-17884: Workpiece administration parameters from pre-1.11 were not converted properly • PRR-17886: No stop message was sent to RundownData if job was finished NOK

<p>1.13.0</p>	<p>12.07.2021</p>	<p>New functionality:</p> <ul style="list-style-type: none"> • REQ-15366 - Support for Celltek tool • REQ-15365 - Added Blink in Reverse LED support for akkutool on mPro software side • REQ-15364 - Merge 1.11.4 • REQ-15374 - Merge 1.12.1 • REQ-15500 - Merge 1.12.2 <p>Bug fixes:</p> <ul style="list-style-type: none"> • PRR-17414 – Previously it was not possible to update tool software for CellTek and Cellcore via mPro – now support software update for CellCore and Celltek is done • PRR-17447 – Wireless tools as noted as “Cleco Cordless Tool” during installation of battery tools • PRR-17057 – Previously it was not possible to change wlan settings of tools via TCP/IP in mpro, now this feature is supported. PRR-17357 – Latched Remote Start option is now disabled properly for Cordless tools as they do not support • PRR-17053 – Seq 31/51 send right MaxTime & MinTime to Measuring Card is fixed. • PRR-15551 – Touch up and Error handling parameter error after factory reset is properly loaded on mPro. • PRR-17496 – Prevailing Torque (PVT) is shown for Seq 32 in runscreen • PRR-17901 – Open protocol Job Status issue reported by customer FCA-Italy/India in MID 35 - 61 is fixed • PRR-18273 – Controller Lockup when input signal status is changed during rundown reported by customer Volvo is fixed • PRR-17574 – TMA software version revision for battery tool is displayed correctly on system bus • PRR-17592 – Tool used to get lock after receiving barcode as described in this PRR is fixed. • PRR-17598 – Tool status was not synchronized properly between mPro & mPro Remote issue is fixed • PRR-17625 – mPro got slower sometimes due to signal queue mishandling is fixed • PRR-17704 – Battery threshold notification for battery tools are updated with levels “Low, High & Medium” • PRR-17796 – Maintenance warning & limit status is correctly displayed to user • PRR-17938 – Various mPro Remote Crashes are fixed • PRR-17938 – correct rf settings options are displayed for TCP/IP connection after tool is identified • PRR-17980 – Saving/loading of application via XML is fixed • PRR-17993 – PATCH_224 is added • PRR-18003 – status of Tool in various cases like uninstall/install (see PRR for various cases) etc are correctly displayed. • PRR-18016 – Transmit power setting for CellCore & CellTek is disabled as it is not supported • PRR-18043 – Tool light setting while rundown is now available for Livewire tools • PRR-18044 – XiBase is updated so that it handles Chinese characters correctly • PRR-18301 – Process Schraube crash / rundown crash is fixed while MID 128 with skip result active in “In Linking Step” mode • PRR-04391 – Torque graph is correctly displayed in various stage case (gap between stages are removed)
<p>1.13.1</p>	<p>17.09.2021</p>	<p>Bug fixes:</p> <ul style="list-style-type: none"> • PRR-18007 – CQA-5604 – parameter reset while booting due to multiple ofmpro connections • PRR-18559 – Neotek scanner deactivated after controller restart • PRR-16590 – Dynamic current calibration is used only after app change • PRR-18601 – Default redundancy is set to Resolver Angle • PRR-18587 – MID40/41 delayed response • PRR-18439 – PRR-18439 - "Use selected Tq unit.." not implemented for ASCII Telegram 2 • PRR-18437 – I-Wrench: switching to FtLbs and back does not work as expected • PRR-18304 – Cannot accept VIN number from OP (MID 50 / 150) • PRR-18258 – VIN cleared at batch done even in Part ID "Enabled" mode • PRR-18065 – Scanner for CellTek deactivated after changing IP • PRR-18125 – schraube crash after barcode with wrong length

1.13.2	28.01.2022	Bug fixes: <ul style="list-style-type: none"> • PRR-18995 - Unexpected barcode while tool is offline • PRR-19090 - Connection with LiveWire tool not stable • PRR-19124 - Print crashes when printing IO parameter to text file • PRR-18364 - Stage number wrong in export • PRR-18782 - Wrong fastener ID recorded in archive • PRR-18715 - MID 35 missing or too late • PRR-19031 - Writing MFU data not possible • PRR-18057 - SA Error with Remote Start (Tool lock failed) • PRR-19087 - ° character wrong with TPS • PRR-19027 - Linking group number not refreshed on run screen • PRR-18791 - Loosening always possible if loosening app is used • PRR-18913 - Different Job/application displayed than selected on mProRemote • PRR-18994 - MID1019 slower than 1000 ms • PRR-19113 - Offline cordless tools recognized as online
1.14.0	15.07.2022	<ul style="list-style-type: none"> • REQ-16048: Implementation of MID0900 open protocol for Angle/Torque trace curve • REQ-16128 - Support TMA Remote Start for Linking modes • PRR-18362: F1 button cannot be used to operate barcode scanner • PRR-18363: Unexpected barcode error when changing sequence program • PRR-19568: Workpiece Picture not updated correctly: tightening position are now updated correctly. • PRR-19685 - VIN input source not granted at SQS Test with 2 tools.
1.14.1	30.09.2022	<ul style="list-style-type: none"> • PRR-19931 – OpenProtocol crash with MID 64 Tightening ID 0 • PRR-20013 – Linking generated NOK in some cases if external linking selection with PLC was used. • PRR-20067 - Seq 80 OR option does not work with Std SW and TPS 2.5.1
1.14.2	07.12.2022	<ul style="list-style-type: none"> • REQ-16339 - Implement MID61 batch status running at field 22 • PRR-19130 –Current value used from previous tool after tool swap - causing IRED errors (Q-Version only) • PRR-20231 - mPro slow and old Tool SN shown (Q-Version only)
1.14.3	25.04.23	<ul style="list-style-type: none"> • REQ-16464 – Automatic acceptance of new tool settings. • PRR-19423 - Reject release can not be acknowledged with Linking Advanced with Scan Part ID Step • PRR-19718 - Sometimes Parameters of CellCore needed to be accepted again after restart controller. • PRR-19931 - 813 - HBPO Vaihingen - FEP crash at GetCalTqFromArchiveRecord() • PRR-20036 - 813 - HBPO Vaihingen - Tool Setup Screen slow • PRR-20097 - 813 - Barcode deleted! at Daimler Thailand MBCKD • PRR-20154 - 813 - HBPO Vaihingen - Cannot deactivate Maintenance Service message • PRR-20228 - 813 Q SW Dynamic Current Calibration not reset after tool swap or chaging calibration values • PRR-20233 - 813 Q SW Speed Reduction not disabled • PRR-20309 - MB Marienfelde Timeout Spiegelung Takt und PG • PRR-20605 - Q SW - Tightening Counter in MID 41 Counter keeps incrementing even after spindle swap • PRR-20610 - AMG UK - last position zero with remote start • PRR-20636 - Q SW - Tool serial changed message in endless loop • PRR-20646 - Bug of printing parameter for ProfiNet and Ethernet • PRR-20818 - PSET_DATA_UPLOAD_REQUEST revision 2 • PRR-20884 - CT Barcode Scanner Issue (Same as PRR-20955) • PRR-20962 - Seq 56 highlighting in programming wrong after toggling graph mode
1.14.4	30.05.23	<ul style="list-style-type: none"> • PRR-21154 - Touchup settings reverted after each restart

<p>1.16.0</p>	<p>25.09.23</p>	<ul style="list-style-type: none"> • REQ-16406 - Add support for CellClutch setting. • REQ-16234 - Calibrated Torque in tool setting should be grayed out. • REQ-16517 - Support OP MIDs for CellClutch • REQ-16194 - Visual tool errors • REQ-16191 - Introduce CellClutch tool type. • REQ-16190 - OK NOK for CellClutch • REQ-16193 - Support batch counter / timeout • REQ-16407 - Add support of a new sequence configuration for cellclutch • REQ-16192 - Support CellClutch version of LiveWire communication • REQ-16490 IPM : From version5 the Life telegram is sent every 5 minutes. • REQ-16486 IPM: Additional ID can be sent with different options. • PRR-19261 Controller does not update the App to be used • PRR-20101 - The Tool still disabled with Reject Release after JOB NOK. • PRR-20347 - F1 button (left button) on CellTek could activate scanner • PRR-20449 - NIO xml Files doesn't close korrekt. • PRR-20633 - 99 character barcode not possible with CellTek • PRR-20676 - Small translation issue in French : replace the name "Broches" by "Outil" • PRR-21050- Automatic SI data transfer not possible with I-Wrench • PRR-21166 - Tool Reverse Still Enabled when using External Tool Enable • PRR-21204 : Cannot reselect the same Linking Group with MID38 when "Terminate Linking Group with MID38" is activated • PRR-21241 - XML/CSV file generated without VIN • PRR-21275 - OP spec violation: Software replies to MIDs 4 and 5 • PRR-21276 - OP spec violation: MID 12 rev 2 : the error is sent in response to MID13. • PRR-21298 - OP spec violation: MID 4 references wrong MID • PRR-21301 - The "Fieldbus Tab" isn't understandable to most of the customers • PRR-21311 - MID064: FEP crashes with empty traces. • PRR-21214 - Evaluation torque in final stage OK if in limit does not work with Tool 16 • PRR-21213 - Process Schraube crash with NOK rundwons with activated Touch up • PRR-21191 - Torque Unit not updated on secondary display
<p>1.16.1</p>	<p>10.10.2023</p>	<ul style="list-style-type: none"> • REQ-16529 - TPS Local PG in Offline Modus: If the TPS connection is aborted, the local PGs are deleted after the configured Timeout has expired. • REQ-16523 Offline TPS 2.1: If the TPS connection is aborted, the MID1019 should have information if the PG has already been loaded and could be used. • PRR-21573 - If the parameters are loaded back after factory reset, the I-Wrench is rewritten as secondary in the tool setup. • PRR-21391 - mPro400 - M40 Ethernet/IP module not working.
<p>1.16.2</p>	<p>19.10.2023</p>	<ul style="list-style-type: none"> • PRR-21723- Installationsfehler is displayed after software update to version 1.16.1-Std
<p>1.16.3</p>	<p>06.03.2024</p>	<ul style="list-style-type: none"> • REQ-16740 - MID0061 – Send Batchstatus without "Batch running". • PRR-15150 - After tool exchange with same model type Tool settings not proper accept. • PRR-19812 - Tool exchange with same tool type - incorrect status in Tool Setup. • PRR-20587 - mPro sw crashes when very high value for evaluation torque is used. • PRR-21171 - Screen turns black under the chinese language. • PRR-21540 - Seq. 97 time-controlled rundown: Angle out of tolerance displayed with rundowns > 65535°. • PRR-21624 - Displayed in GUI in "IP Address/HostName "" when installing a cordless tool. • PRR-21735 - Tool stops in 1st stage with TMAX error. • PRR-21900 - The Part-ID is not mirrored if the Input "Tool Group Enable" is set. • PRR-21907 - Default parameter for backoff CellClutch are 0%. • PRR-21978 - Default Setup Values for Clutch. • PRR-22074 – Linking mode: Liwewire Tool sends double result of the last position after reconnecting. • PRR-22083 – the Message "waiting for socket selection" pop up though no socket tray is configured. • PRR-22086 – CSV file is not set after NOK result. • PRR-22115 - Workpiece number not always displayed in Archive. • PRR-22116- OP MID-0076 incorrect with I-Wrench. • PRR-22171- Basic Programming needs confirm changes although nothing changed.

1.16.4	19.03.2024	<ul style="list-style-type: none"> • REQ-16754-Barcode Position Selection: Now it is possible to accept shorter workpiece number as selected. • REQ-16760 MID0061 Revision 4: Added option to transmit VIN Number with Max.39 chars into VIN and VIN2. • REQ-16776 XML/CSV Data Transmission: CSV file content extended with "CsvResultId" number. Helps to identify that there were two results within one second. • REQ-16777-Tubnut left rotation settings: The max torque of the opening cycle/left rotation is now at least 0.75 Nm. Solves issues with very small tool capacities.
1.16.5	22.10.2024	<ul style="list-style-type: none"> • REQ-16960. Web server can be switched off • PRR-17576: Reassign tool button did not work properly • PRR-23111: MID 18 no longer worked
1.16.6 S168813	14.10.2024	<p>Main change / reason for new version:</p> <ul style="list-style-type: none"> • REQ-16960 Webserver can be switched off in the Communications settings. By default, it must be on. • REQ-16962 implement PATCH_285: Detect parameter set upload errors. <p>Bugs fixes:</p> <ul style="list-style-type: none"> • PRR-22773 - Tightening process would crash if a group with 16 tools was programmed. • REQ-17038: Improved handling of battery tool results • PRR-23174: Under some circumstances, battery tools could re-use a result ID • PRR-23208: High activity when battery tool needed maintenance • PRR-23209: High activity when cable tool was programmed but not connected
2.0.5	03.06.2024	<p>First version common source code for mPro300 and mPro400</p> <ul style="list-style-type: none"> • Support both screen sizes with mPro Remote. mPro Remote is now using 4:3 screen format for the MPSW for better usability. • Added support for 250 applications • Added support for 250 jobs • Added support for 250 bitmaps • Added new languages Slovak and Serbian • Synchronized features which were only available in the S168813 to the MPSW300 and visa versa. (e.g. Offline Options for TPS 2.1, M40 Ethernet IP Module, MID0061 option "Batch running", Barcode Position Selection, XML/CSV result optimizations, ...) • Updated all components and modules. <p>Parameters are upgraded from 1.x version to the 2.x version. But it's NOT possible to load parameter from the 2.x version to a 1.x version (downgrade).</p>
2.0.6	02.08.2024	<p>Main change / reason for new version:</p> <ul style="list-style-type: none"> • PRR-22746 – Reduced Display flickering, especially when the controller is under heavy load. • PRR-21490 – Behaviour on the the FMK error / EMS error 22007 improved. Load situation improved, so the error is not happening that often.
2.0.7	26.08.2024	<p>Main change / reason for new version:</p> <ul style="list-style-type: none"> • REQ-16915: Update measurement card version to S168025-641-R14941 (f95490).

2.1.0 S168813 MPSW300	14.11.2025	<p>New Features / Enhancements:</p> <ul style="list-style-type: none"> Req-15411, Req-15767, Req-15769, Req-15770, Req-15771, Req-15772, Req-16731: Added TPS version 3.2. Req-16801-Added controller reboot button in diagnostic menu. Req-15783 - Changed Tab Name in Communications menu from Fieldbus to Protocol Settings. <p>Bugs fixes:</p> <ul style="list-style-type: none"> PRR-22176 –Livewire Tool: Only 21 Byte from the Part ID are mirrored to the PLC. Now is possible to mirror the whole Part ID. PRR-22202 –SEQ 31: The Red Evaluation Boxes for pass fail windows in the torque graph with two traces y-axis (Toque, Torque Red) do not display correctly of the controller screen: Now the both graph are displayed with the same scaling. PRR-22582 -Chinese not working correctly on statistics menu. Now PRR-22593 - License Manager button is visible in the mPro300. PRR-22650, PRR-22719 - VIN disappears if the same Linking number is sent again. Now only the linking number is reset. PRR-22663, PRR-22723 - TCP Client with error message Bad length, when a new PG is set during the Tightening. Now the TCP Telegram is set correctly to the TorqueNet. PRR-22664 - MID 0071: Sometimes the error 139 is not sent after the Tool is Disabled. Now the error 139 is sent for one time. PRR-22724 – Display flickering when booting up the controllers.
2.1.1 S168813 MPSW300	16.12.2024	<p>New Features / Enhancements:</p> <ul style="list-style-type: none"> REQ-17096 - The torque values over 10000 Nm can be transmitted via Open Protocol and fieldbus. REQ-17100 - Swap the data sending float tightening results via fieldbus in Little-Endian mode. <p>Bugs fixes:</p> <ul style="list-style-type: none"> PRR-23344 – mPro300: After software update from v2.0.x to v2.1.0 the batram parameters are deleted.
2.2.0 S168813 MPSW300 BTSW	05.02.2025	<p>New Features / Enhancements:</p> <ul style="list-style-type: none"> REQ-16895 - CPSi Diagnostics added, improved diagnostics options for PDMi REQ-17077 - Added an output signal "Fieldbus running" to indicate that the fieldbus is running. REQ-16960 - Webserver can be switched off in the Communications settings. By default, it is on. REQ-16711 - After resetting the Anybus module, the controller does not need to be restarted. REQ-16712 - F-Address for PROFINET can be set. <p>Bug Fixes (Customer Claim):</p> <ul style="list-style-type: none"> PRR-23270 - mPro doesn't send the selected program ID to the open protocol in linking mode. PRR-20874 - mPro300 does not accept part id anymore. PRR-21078 - mPro300 screen blanks out over time while in normal operation. PRR-21736 - mPro300 BD Spindle is not starting with EMS error. PRR-21816 - mPro300 "RES?" error: MC receives start signal from mPro but somehow does not start rundown. PRR-23227 - mPro400 - NTP-Date/Time synchronization does not work. PRR-23373 - NOK statistics did not show values if too many tightenings were made. PRR-23478 - mPro300 is getting slow or can stop working in some installations.
2.3.0 CTSW	28.02.2025	<p>New Features / Enhancements:</p> <ul style="list-style-type: none"> REQ-17134 - Initial Release for hardware platform mProConnect (CellTek based).