

## STMD-SW change list

SW-Version	SW-Datum	Extensions	Fixes
S168025-500	20.10.2017	Initial release: - DGD communication protocol, which gives advantages in: o Multi-spindle configuration o Error Handling o Compatibility with STMH/STMHE Tightening Modules. o Easy migration of special mPro400 software to Hybrid platform.	
S168025-501	22.11.2017	Updated 17 series motor parameters	Improve accuracy for soft stop speed. Tq factor was always 0
S168025-502	13.02.2018		Fixed controller lockup (Improved parameter transmission)
S168025-503	26.02.2018		Improved angle accuracy
S168025-504	13.04.2018	Secondary display support Service and cable counter support	
S168025-505	10.08.2018	FINDINI and OTINI support	Stop rundown immediately when physical startbutton released (instead to wait for stop-command from mPro); Seq35 fixes; quickstop-timeout as warning (instead of error); Add keep-alive for diagnostic speed-test;
S168025-506	08.10.2018	Adjustable NeoTek LEDs brightness supported Forced NOK supported Seq 80 shutoff-torque-AND-angle supported	
S168025-507	23.11.2018	Includes support for <i>Accessory 2D Reader (937731PT, 942391PT, 942394PT)</i>	
S168025-506.1	11.01.2019		PRR-13226 fixed
S168025-508	08.02.2019	Includes support for <i>Accessory Toollight</i>	
S168025-509	26.03.2019	Added feature "Torsion-Compensation", and added configuration for 48EAE Tool with Engel motor (PS36)	
S168025-510	28.05.2019	Includes support for NeoTek Gyroscope <i>Accessory</i>	
S168025-610	20.09.2019	Initial release for STMD-H 961905PT , same features as S168025-510	
S168025-612	20.12.2019	• REQ-14284 - Support for HW Rev 3. • PRR-11548 - Parametrizable ramps.	• PRR-15317 – Display HW version in SystemInfo.
S168025-515	26.02.2020	Reformat internal flash memory with ecc enabled. Downgrade to versions prior to 515 not possible.	
S168025-516	23.04.2020	REQ-14734 - NAND Upgrade	
S168025-517	02.07.2020	REQ-14801 - Software ECC in NAND REQ-14802 - Bootloader for Software ECC	

## STMD-SW change list

SW-Version	SW-Datum	Extensions	Fixes
<b>S168025-518 / 618</b>	17.07.2020	Features: • REQ-14597 – Tag Accessory support • REQ-14726 – TubeNut support  Bugfixes: • PRR-15464 - Seq13 evaluation different as with STMH module • PRR-15756 – Broken error Handling • PRR-16310 - Wrong temperature measurement in rev3B	Features: • REQ-14597 – Tag Accessory Unterstützung • REQ-14726 – TubeNut Unterstützung  Bugfixes: • PRR-15464 - Seq13 Auswertung anders wie STMH • PRR-15756 – Fehlerhafte Nacharbeit • PRR-16310 - Falsche Temperaturmessung in rev3B
<b>S168025-519</b>	03.09.2020	Bugfixes: • PRR-16468 - Software update was not possible from version 515 or 516	Bugfixes: • PRR-16468 - Software update war nicht möglich von der Version 515 oder 516
<b>S168025-620</b>	17.09.2020	Bugfixes: • PRR-16506 - No graphic-point for exact MS-reached angle • PRR-16501 - Touch screen does not work correctly on Secondary	Bugfixes: • PRR-16506 - Kein Grafikpunkt für exakten MS-Punkt • PRR-16501 - Touch screen hat nicht beim Secondary funktioniert
<b>S168025-521_621</b>	16.10.2020	Features: • REQ-14639 - Read/Write MFU Data • REQ-14805 - Read service counter range and factors  Bugfixes: • PRR-16991 - Slow communication between primary and secondary controllers	Features: • REQ-14639 - MFU Daten Lesen/Schreiben • REQ-14805 - Service Zähler Faktoren und Bereiche lesen.  Bugfixes: • PRR-16991 - Langsame Kommunikation zwischen Primary und Secondary
<b>S168025-522_622</b>	26.02.2021	Features: • Hard-reset tool (TIM) when communication with tool fails (tool-not-connected issue REQ-15363)	Features: • TIM-Spannung ab/anschalten falls Kommunikation mit Tool nicht funktioniert (REQ-15363)
<b>S168025-523_623</b>	03.03.2021	Features: • REQ-15297 Support speed in Deci-RPM accuracy with 1 decimal place	Features: • REQ-15297 Drehzahl mit 1/10 Genauigkeit unterstützt
<b>S168025-624</b>	20.05.2021	•REQ-15499 - Support new display	•REQ-15499 - Support new Display
<b>S168025-524</b>	20.05.2021	•PRR-17909 - STMD Software crashes with Seq31 and 51	•PRR-17909 - STMD Software Absturz mit Seq31 und 51
<b>S168025-625</b>	17.06.2021	•PRR-18040 very high negative torque in archive graph •PRR-18136 analog-tool offset error	•PRR-18040 very high negative torque in archive graph •PRR-18136 analog-tool offset error
<b>S168025-525</b>	21.06.2021	•PRR-17614 patch uboot to change memory frequency to 504MHz •PRR-18040 very high negative torque in archive graph •PRR-18136 analog-tool offset error	•PRR-17614 patch uboot to change memory frequency to 504MHz •PRR-18040 very high negative torque in archive graph •PRR-18136 analog-tool offset error
<b>S168025-626</b>	11.08.2021	•Support of BD-Spindle •Support of BD-Minispindle	•Support of BD-Spindle •Support of BD-Minispindle

## STMD-SW change list

SW-Version	SW-Datum	Extensions	Fixes
<b>S168025-527</b>	14.09.2021	<ul style="list-style-type: none"> <li>•Fix CRC-error on 18 / 48 tools (PRR-18605)</li> <li>•In case BD-spindle connected, show info that it is not supported by 5xx series (REQ-15752)</li> </ul>	<ul style="list-style-type: none"> <li>•Fix CRC-error on 18 / 48 tools (PRR-18605)</li> <li>•In case BD-spindle connected, show info that it is not supported by 5xx series (REQ-15752)</li> </ul>
<b>S168025-627</b>	14.09.2021	<ul style="list-style-type: none"> <li>•Fix CRC-error on 18 / 48 tools (PRR-18605)</li> <li>•Fix AN2F-error when current-redundancy enabled on BD-minispindle (PRR-18522)</li> </ul>	<ul style="list-style-type: none"> <li>•Fix CRC-error on 18 / 48 tools (PRR-18605)</li> <li>•Fix AN2F-error when current-redundancy enabled on BD-minispindle (PRR-18522)</li> </ul>
<b>S168025-528</b>	24.11.2021	<ul style="list-style-type: none"> <li>•REQ-15790 - STO-state as TM_DIDO input</li> <li>•REQ-15808 - Increase SSIO-Clk drive strength</li> </ul>	<ul style="list-style-type: none"> <li>•PRR-12885 - Date/time for EMS-entry incorrect</li> <li>•PRR-17390 – Sporadic servo-initialization error after reboot</li> <li>•PRR-17538 – Service-counter-areas wrong when set first time with TSI-viewer</li> <li>•PRR-18742 – Sporadic log-messages with no content</li> </ul>
<b>S168025-628</b>	24.11.2021	<ul style="list-style-type: none"> <li>•REQ-15790 - STO-state as TM_DIDO input</li> <li>•REQ-15808 - Increase SSIO-Clk drive strength</li> </ul>	<ul style="list-style-type: none"> <li>•PRR-12885 - Date/time for EMS-entry incorrect</li> <li>•PRR-17390 – Sporadic servo-initialization error after reboot</li> <li>•PRR-17538 – Service-counter-areas wrong when set first time with TSI-viewer</li> <li>•PRR-18742 – Sporadic log-messages with no content</li> </ul>
<b>S168025-529</b>	12.01.2022		<ul style="list-style-type: none"> <li>•PRR-19133 – Speed displayed negative for odd-gearing tools</li> <li>•PRR-19128 – False transducer-calibration offset-alarm</li> </ul>
<b>S168025-629</b>	12.01.2022		<ul style="list-style-type: none"> <li>•PRR-18424 - BDU-spindle torque measured negative</li> <li>•PRR-19133 – Speed displayed negative for odd-gearing tools</li> <li>•PRR-19128 – False transducer-calibration offset-alarm</li> </ul>
<b>S168025-530</b>	not yet		
<b>S168025-630</b>	14.01.2022	<ul style="list-style-type: none"> <li>•REQ-15969 – Support odd-gearing at output-drive</li> <li>•REQ-15974 - Seq35 should support angle as parameter (not set parameter-error shutoff when angle too low/high)</li> </ul>	
<b>S168025-531</b>	07.03.2022	<ul style="list-style-type: none"> <li>•REQ-15969 – Support odd-gearing at output-drive (not relevant for v5xx, since they do not support BD-spindles)</li> <li>•REQ-15974 - Seq35 should support angle as parameter (not set parameter-error shutoff when angle too low/high)</li> </ul>	<ul style="list-style-type: none"> <li>•PRR-18980 – Various measurement-card errors (IREN, FMK), due to timing issues in v5xx version</li> <li>•PRR-19272 – Stage-result was sent twice to controller, if rundown was aborted before final stage</li> </ul>
<b>S168025-631</b>	07.03.2022		<ul style="list-style-type: none"> <li>•PRR-18980 – Various measurement-card errors (IREN, FMK), due to timing issues in v5xx version (not relevant for v6xx, since faster than v5xx)</li> <li>•PRR-19272 – Stage-result was sent twice to controller, if rundown was aborted before final stage</li> </ul>
<b>S168025-532</b>	26.07.2022		<ul style="list-style-type: none"> <li>•PRR-19797 – Gyroscope GCOM error when ToolHeadAngle entry is missing</li> <li>•PRR-19799 – Gyroscope correction reversed with negative tool speed</li> <li>•PRR-19747 – Maintenance-counter systemwarning sent, even if controller do not use maintenance-counter</li> </ul>

## STMD-SW change list

SW-Version	SW-Datum	Extensions	Fixes
<b>S168025-632</b>	26.07.2022		<ul style="list-style-type: none"> <li>•PRR-19797 – Gyroscope GCOM error when ToolHeadAngle entry is missing</li> <li>•PRR-19799 – Gyroscope correction reversed with negative tool speed</li> <li>•PRR-19747 – Maintenance-counter systemwarning sent, even if controller do not use maintenance-counter</li> </ul>
<b>S168025-533</b>	23.09.2022	<ul style="list-style-type: none"> <li>•REQ-15813 - Snugpoint detection on the fly</li> <li>•REQ-16112 - Support flexible extended parameterset</li> <li>•REQ-16113 - Automatic speed-change in new Seq35 variant</li> <li>•REQ-16197 - Patch motor-parameters to prevent too early i2c-error</li> <li>•REQ-16198 - New output-head parameters in SIM for gear-translation and efficiency</li> </ul>	<ul style="list-style-type: none"> <li>•PRR-19523 - Support STMD-H 961905PT-XS7</li> </ul>
<b>S168025-633</b>	23.09.2022	<ul style="list-style-type: none"> <li>•REQ-15813 - Snugpoint detection on the fly</li> <li>•REQ-16112 - Support flexible extended parameterset</li> <li>•REQ-16113 - Automatic speed-change in new Seq35 variant</li> <li>•REQ-16197 - Patch motor-parameters to prevent too early i2c-error</li> <li>•REQ-16198 - New output-head parameters in SIM for gear-translation and efficiency</li> <li>•REQ-16032 - Dump ethernet-statistic in log-file (in case of missing packets)</li> </ul>	<ul style="list-style-type: none"> <li>•PRR-19523 - Support STMD-H 961905PT-XS7</li> </ul>
<b>S168025-534</b>	27.10.2022		<ul style="list-style-type: none"> <li>•PRR-18193 - Seq16 is not functional, error RES occur</li> <li>•PRR-19825 - Gyro error at start of second stage</li> </ul>
<b>S168025-634</b>	27.10.2022		<ul style="list-style-type: none"> <li>•PRR-18193 - Seq16 is not functional, error RES occur</li> <li>•PRR-19825 - Gyro error at start of second stage</li> </ul>