

Release for Production



		SOFTWARE	
Change Notification (AE)	Scope: Global Production	No.: AE070_2024	

Distribution	G	SL	PD	PDM	OM	QA	ENH Lorenz Laden- burger	RD	SE	PP	PM	ENH	EN	AE	RDL	RDE	RDA	Total	
Sheet 1			X			X	X	X	X		X		X	X	X		X	X	10
Serial Sheet																			

Software for mPro300 MPSW300-2.1.0-Std

m-Pro-SW

- Software: MPSW300-2.1.0-Std from 2024-11-18, GIT hash 7ad175
- Required Sysdisk: S169258-1.1-418-gfdbfcf3
- Base: MPSW300-2.0.6-Std
- Development Environment: devenv-ix7-sdk-1.x 1.0-3
- Linked mc version: S168025-643-R15030 (2e6f25)
- Languages: German, English, Chinese, Polish, Spanish, Italian, Czech, French, Portuguese, Russian, Slovak, Serbian
- Configuration: 16 Tool Groups, 16 Tools, 250 Applications, 96 Steps, 250 Bitmaps (Pictures)

Main Changes / Enhancements to Version 2.0.7-Std:

- Req-15411, Req-15767, Req-15768, Req-15769, Req-15770, Req-15771, Req-15772: Added TPS version 3.2.
- Req-16801 - Added controller reboot button in diagnostic menu.

Bug Fixes (Customer Claim):

- PRR-22176: Livewire Tool: Only 21 Byte from the Part ID were mirrored to the PLC.
- PRR-22202: SEQ 31: The NOK windows did not display correctly with two y-axes active.
- PRR-22582: Chinese language was not working correctly on statistics menu.
- PRR-22593: License Manager button was visible
- PRR-22650, PRR-22719: VIN disappeared if the same Linking number was sent again
- PRR-22663, PRR-22723: TCP Client error message Bad length appeared in Syslog
- PRR-22664: MID 0071: Sometimes the error 139 was not sent after the tool was disabled
- PRR-22724: Display flickered when booting up the controllers.
- PRR-22759: MID 38 was not accepted if job was aborted while no job was running.
- PRR-22773: Tightening process would crash if a group with 16 tools was programmed
- PRR-22941: Disabling the TorqueNet logon service twice would cause controllers to no reconnect after.
- PRR-22965: In measurement table, the field TP would be cleared for sequences 30.
- PRR-22975: On ToolsNet, under certain circumstances, mPro could stop sending keep-alive messages when the system clock was set.

Target Hardware:	mPro300
Link to GIT/SVN:	http://euqitlab.atg.root/mprosw/s168300/-/tags/v2.1.0-Std

For request to:			
AE	<input checked="" type="checkbox"/> - for consideration at new disposition	SE	<input checked="" type="checkbox"/> - for consideration at service benefits
	<input type="checkbox"/> - first consume old stock	SL	- information to all external agent representatives
	<input type="checkbox"/> - rework stock	EN	- creating material data in SAP
	<input checked="" type="checkbox"/> - for consideration at operation	PD	- ordering
<input checked="" type="checkbox"/> - information to all mechanics	- current orders		
RDS /	<input checked="" type="checkbox"/> - for consideration at new conception		- debut price
ENS /	<input checked="" type="checkbox"/> - for consideration at software duplication	RDL	- update test beds
ENH	- update test beds		

	Editor:	Auditor:	Inspector:	Approval:	Order number:
Date	20.11.2024	20.11.2024	20.11.2024	20.11.2024	
Name	Ouaddane, Ismail <i>RDS/ENT</i>	Schips, Patrick <i>RDS/ENT</i>	Köhn, Volker <i>RDL</i>	Kogel, Manfred <i>RD/EN</i>	