



Änderungsindex Software S168691

Release notes software S168691

Version	English
101.0	Main Changes / Features: <ul style="list-style-type: none"> • Parameter Backup Service <ul style="list-style-type: none"> ◦ Windows Service to create automatic backups of parameters. • Display of sysdisk and software versions in the overview of controllers. • Update of software through tree structure (SW update on several controllers). • Install and uninstall of licenses for the use of the functions Backup Tool und SW Update.
102.0	Main Changes / Features: <ul style="list-style-type: none"> • REQ-12663 – Updated to XiBase9 Version 7 • REQ-12879 – Allow updating the controller tree without password • PRR-11141 – English and French GUI texts incomplete • PRR-11071 – Errors in Licence Manager manual • PRR-11860 – Crash if xml log file gets too big • PRR-11599 – mProRemote did not support more than 7 Windows (now 30 are supported) • PRR-11851 – Cannot load controller tree configuration
102.1	Main Changes / Features: <ul style="list-style-type: none"> • PRR-13854 - Selection for other application in Application builder is disappearing sometimes • PRR-13556 - WinRemote Menüleiste nicht vorhanden bzw falsch gezeichnet • PRR-13221 - BROSE Fehlermeldungen mit Professional Version • PRR-13042 - Stufen Farben nicht mehr vorhanden • PRR-14040 - Audi BRX 821 - LW Stage list incorrect • PRR-13839 - BROSE Edit Button im SI Fenster fehlt • PRR-13137 - Visu Bilder werden nicht angezeigt • PRR-13857 - WinRemote - Conf. manager Tool group 4 not selectable • PRR-13436 - WinRemote - Dynamisches platzieren von Objekten nicht möglich • PRR-13912 - Maske Statistik wird nicht korrekt angezeigt • PRR-13526 - SSH connections not always closed
2.2	Main Changes / Features: <ul style="list-style-type: none"> • REQ-14403 - Update Licensing runtime • PRR-13341 - Grey boxes behind tightening positions • PRR-14538 - Black area in SAMBA Test screen
2.3	Main Changes / Features: <ul style="list-style-type: none"> • REQ-14458 - Need multiple connections to the same controller at once • PRR-15519 - Unhandled Exception in Update Tree View • PRR-15522 - Executables in XiBase9 PC Runtime not signed
2.4	Main Changes / Features: <ul style="list-style-type: none"> • PRR-12919 - Error because of bad TreeView XML • PRR-13819 - Bad prompt via telnet connection received • PRR-14133 - AutoBackupStatus.xml defect • PRR-14135 - Deleting cache files is not activated by default • PRR-15289 - Many log messages after software update • PRR-15658 - Exception message after adding a controller • PRR-15861 - Crash after stopping software update • PRR-15864 - Crash after selecting "Details" in File select box
2.4.1	Main Changes / Features: <ul style="list-style-type: none"> • PRR-17023 - AFO Button in Joint Number screen missing in Software S168833 • PRR-17379 - TM Download does not work (mPro Software also must be up to date)
2.5.0	Main Changes / Features: <ul style="list-style-type: none"> • REQ-15373 - Show controller info and support Remote Parameter Backup for mPro300

