

Release for Production



SOFTWARE	
Change Notification (AE)	Scope: Global Production
No.: AE010_2022	

Distribution	G	SL	PD	PDM	OM	QA	ENH Lorenz Laden- burger	RD	SE	PP	PM	ENH	EN	AE	RDL	RDE	RDA	Total	
Sheet 1			X			X	X	X	X		X		X	X	X		X	X	10
Serial Sheet																			

Software for mPro200GC & mPro400GC(D) S168813-1.13.2-Std

- Software: S168813-1.13.2-Std from 20.05.2022, SVN-Revision 64508
- Required Sysdisk: S169372-214
- Base: S168813-1.13.1-Std
- Development Environment:
 MWOSPPC tag http://htwe0011/svn/Tools/HAWK/tags/HAWK_2.5.5.1_DBG_2.5.10.0_OS_5.2_xcc_3.4_ed110_r2
 Xibase9 tag <http://htwe0011/svn/Components/XiBase/tags/7406R44/PPC/dev>
 Arcman tag <http://htwe0011/svn/Components/ArcMan/tags/917/PPC5200>
 mProPrecompileComponents tag http://htwe0011/svn/Components/mProPrecompiledComponents/tags/1.100.0_R15015/export
- Languages: German, English, Chinese, Spanish, Polish, Portuguese, Italian, French, Russian
- Configuration: 16 Tool Groups, 16 Tools, 99 Applications, 6 Stages Operation

Short description / main change / reason for new version:

- Bugfixes

Main Changes / Enhancements to Version 1.13.1-Std:

- PRR-18995 - Unexpected barcode while tool is offline
- PRR-19090 - Connection with LiveWire tool not stable
- PRR-19124 - Print crashes when printing IO parameter to text file
- PRR-18364 - Stage number wrong in export
- PRR-18782 - Wrong fastener ID recorded in archive
- PRR-18715 - MID 35 missing or too late
- PRR-19031 - Writing MFU data not possible
- PRR-18057 - SA Error with Remote Start (Tool lock failed)
- PRR-19087 - ° character wrong with TPS
- PRR-19027 - Linking group number not refreshed on run screen
- PRR-18791 - Loosening always possible if loosening app is used
- PRR-18913 - Different Job/application displayed than selected on mProRemote
- PRR-18994 - MID1019 slower than 1000 ms
- PRR-19113 - Offline cordless tools recognized as online
- PRR-17678 - MID 42 took too long
- PRR-19290 - MID 35 status rev < 4 incorrect
- PRR-18985 - ToolsNet trace: Angle scale wrong if tightening did not reach last stage
- PRR-19365 - RES? Error with release sequence with BTS tools with application > 6
- PRR-19428 - Remote start livewire tools could sometimes start the wrong application
- REQ-16014 - Added option to clear job selection at end of job

Target Hardware:	mPro200GC, mPro200GC-AP, mPro400GC, mPro400GCD
Link to Tag in SVN:	http://10.122.65.142/svn/mProSw/CS/tags/release/1.13.2-Std-64507

For request to:			
AE	<input checked="" type="checkbox"/> - for consideration at new disposition	SE	<input checked="" type="checkbox"/> - for consideration at service benefits
	<input type="checkbox"/> - first consume old stock	SL	<input type="checkbox"/> - information to all external agent representatives
	<input type="checkbox"/> - rework stock	EN	<input type="checkbox"/> - creating material data in SAP
	<input checked="" type="checkbox"/> - for consideration at operation	PD	<input type="checkbox"/> - ordering
RDS / ENS / ENH	<input checked="" type="checkbox"/> - information to all mechanics		<input type="checkbox"/> - current orders
	<input checked="" type="checkbox"/> - for consideration at new conception		<input type="checkbox"/> - debut price
	<input checked="" type="checkbox"/> - for consideration at software duplication	RDL	<input type="checkbox"/> - update test beds
	<input type="checkbox"/> - update test beds		

	Editor:	Auditor:	Inspector:	Approval:	Order number:
Date	02.06.2022	02.06.2022	02.06.2022	02.06.2022	
Name	Wichmann, Markus <i>RDS/ENT</i>	Schips, Patrick <i>RDS/ENT</i>	Köhn, Volker <i>RDL</i>	Kogel, Manfred <i>RD/EN</i>	