# **Release for Production**



	SOFTWARE	
Change Notification (AE)	Scope: Global Production	No.: AE_104_2019

Distribution	G	SL	PD	PDM	ОМ	QA	ENH Lorenz Laden- burger	RD	SE	PP	PM	ENH	EN	AE	RDL	RDE	RDA	Total
Sheet 1			X			Х	X	Х	Х		Х		Х	Х	Х		Х	10
Serial Sheet																		

## Software for WLAN Socket Tray S169280-102-R1434

The Software S169280-102-R1434 for WLAN socket tray (Controller-Platine Rev.2) is released for production.

#### Bug fixes

- PRR-14471: Buffer Battery not used correctly
- PRR-14470: Disconnection of Battery during booting not working
- PRR-14487: WLAN connection issues during EMC testing

#### Requirements

REQ-14059: Support new CPU Hardware

### Known limitations:

- only Odin WLAN module is supported; for SRD communication an ODIN firmware ODIN-W26X-SW-7.0.0-090 or newer is necessary;
- Software only works with new hardware: Controller-Platine Rev.2

Software Date: 05.08.2019

Development Environment: Atollic Truestudio 9.02

GCC Version 6.3.1

Target Hardware: WLAN Socket Tray 4/8 943610PT, 9436xxPT

Link to Tag in SVN: ait@west012.atg.root:stm32/SocketTray.git, S169280\_102\_1434\_8e8011

For r	eque	est to:				
	X	- for consideration at new disposition	SE	х	- for consideration at service benefits	
AE		- first consume old stock	SL		- information to all external agent representatives	
		- rework stock	EN		- creating material data in SAP	
	X	- for consideration at operation			- ordering	
	Х	- information to all mechanics	PD		- current orders	
RDS / ENS / ENH	Х	- for consideration at new conception			- debut price	
	X	- for consideration at software duplication	RDL		- update test beds	
		- update test beds				

	Editor:	Auditor:	Inspector:	Approval:	Order number:
Date	5,8.2019	5.8.10	05.08.2019	5. 8. 18/	
Name	RDH Roilsmayer Ottoms	RDH P.L.	RDL M. Opferkuch	RD/EN M. Kogel	